Heli-One Colorado

QAD-1032 Exte
Heli-One Americ
FAA CRS LH3D657L / EASA 14

HELI-ONE COLORADO EXTERNAL REPAIR TAG

EXTERNAL REPAIR TAG (UNSERVICEABLE PART)

CM # 71571		CUSTOMER NAME: HPN	
PART NAME: Bearing Support		QUANTITY: 1	REPAIR WORK REQUESTED: Inspect
PART NO: 0292805060		SERIAL NO: 2393PR	
TSN: UNK	TSO: UNK	CSN: N/A	CSO: N/A

REMOVED FROM

	SERIES:		VARIANT:			MODULE #		
●	ENGINE TSN:	ENGINE TSO:	TSN-GEN	TSO-GEN	CSN-GEN	TSN-FT	TSO-FT	CSN-FT
	ENGINE S/N:							
	MODULE S/N:							
○	COMPONENT NAME:							
	COMPONENT P/N:		TSN	TSO	CSN	CSO		
	COMPONENT S/N:							
○	AC MODEL:	AC S/N:	REGISTRATION #		TOTAL TIME:	TOTAL CYCLES:		

REASON FOR REMOVAL / REPAIR(S) REQUIRED: Part requires Overhaul Inspection

DATE REMOVED: 2/26/2016

TECH STAMP

NOTE ON THE REPAIR ORDER THAT INSPECTED, REPAIRED OR OVERHAULED PARTS RETURNED TO HELI-ONE MUST ACCOMPANY FAA FORM 8130-3, EASA FORM 1 OR EQUIVALENT.