HELI-ONE COLORADO EXTERNAL REPAIR TAG

EXTERNAL REPAIR TAG (UNSERVICEABLE PART)								
CM # 71571			CUSTOMER NAME: HPN					
PART NAME: FT NGV			QUANTITY: 1		REPAIR WORK REQUESTED: Inspect			
PART NO: 0292500010			SERIAL NO: 308LT					
TSN: N/A	TSO: N/A		CSN: N/A	N/A	CSO: N/A	N/A		

REMOVED FROM								
☐	SERIES: _____		VARIANT: _____			MODULE # _____		
	ENGINE TSN: _____	ENGINE TSO: _____	TSN-GEN	TSO-GEN	CSN-GEN	TSN-FT	TSO-FT	CSN-FT
	ENGINE S/N: _____		_____	_____	_____	_____	_____	_____
	MODULE S/N: _____		_____	_____	_____	_____	_____	_____
☐	COMPONENT NAME: _____							
	COMPONENT P/N: _____		TSN	TSO		CSN		CSO
	COMPONENT S/N: _____		_____	_____		_____		_____
☐	AC MODEL: _____	AC S/N: _____	REGISTRATION # _____	TOTAL TIME: _____		TOTAL CYCLES: _____		

REASON FOR REMOVAL / REPAIR(S) REQUIRED: Returned to customer as is, requires Overhaul Inspection to determine servicability.	DATE REMOVED	TECH STAMP
NOTE ON THE REPAIR ORDER THAT INSPECTED, REPAIRED OR OVERHAULED PARTS RETURNED TO HELI-ONE MUST ACCOMPANY FAA FORM 8130-3, EASA FORM 1 OR EQUIVALENT.	12/7/2017	HELI-ONE 017 QUALITY DELEGATION