HELI-ONE COLORADO EXTERNAL REPAIR TAG

EXTERNAL REPAIR TAG (UNSERVICEABLE PART)								
CM # 69370			CUSTOMER NAME: HPN					
PART NAME: Diffuser			QUANTITY: 1			REPAIR WORK REQUESTED: Inspect		
PART NO: 0292208190			SERIAL NO: 2390B					
TSN: O/C	TSO: N/A		CSN: N/A	N/A		CSO: N/A	N/A	

REMOVED FROM								
	SERIES: Arriel 1		VARIANT: 1C			MODULE # M03		
◉	ENGINE TSN: N/A	ENGINE TSO: N/A	TSN-GEN	TSO-GEN	CSN-GEN	TSN-FT	TSO-FT	CSN-FT
	ENGINE S/N: N/A		N/A	N/A	N/A	N/A	N/A	N/A
	MODULE S/N: 9455		8389	1884	Unknown	N/A	N/A	N/A
○	COMPONENT NAME: _____							
	COMPONENT P/N: _____		TSN	TSO		CSN	CSO	
	COMPONENT S/N: _____		_____	_____		_____	_____	
○	AC MODEL: _____	AC S/N: _____	REGISTRATION # _____	TOTAL TIME: _____		TOTAL CYCLES: _____		

REASON FOR REMOVAL / REPAIR(S) REQUIRED: Return to customer as is, requires Inspection to determine serviceability	DATE REMOVED	TECH STAMP
NOTE ON THE REPAIR ORDER THAT INSPECTED, REPAIRED OR OVERHAULED PARTS RETURNED TO HELI-ONE MUST ACCOMPANY FAA FORM 8130-3, EASA FORM 1 OR EQUIVALENT.	12/4/2017	HELI-ONE 024 REPAIR CENTER