Tempest Aviation Group Inc

Unit 100 2092 Enterprise Way Kelowna, BC Canada V1Y 6H7

DESC: UNIT, ROTOR RPM WARNING

PN: G3001-02 SN: N/A

COND: AR Qty: 1

LOC: ARM0122 CTRL#: 99194 ID#: 1

REMOVAL INFORMATION

AC MODEL: AS350B2 SN: 2635 LOT: 179

REMOVED @ T.A.F.T. = 10894.3 Hrs. PO#: P14726

REASON FOR REMOVAL: SV AC PART OUT

WORK REQUIRED: INSPECT AND RE-CERTIFY

DATE: 10/3/2017 RECEIVED BY: Mike MacAdams

1789

Desc: Unit, Rotor RPM

PN: 63001-02

SN: 012

Removal Information:

AS350B2 A/C SN: 2635 LOT#: 179

T.A.F.T. = 10894.3 HRS PO#: P14726

Reason For Removal:

Servicable Aircraft Part Out

Date: ~~Sept~~ Oct 2/17 Signature: