

# SERVICEABLE

☐ Repair ☐ Overhaul ☑ Inspection

Customer LFAV

Manufacturer

Reg _____ AFTT _____

Part Name Tube Assy.

Part Number 350A52-1088-00

Part Serial # NSN

TSN _____ TSO _____

TREM _____ Cycles _____

CREM _____ CSN _____

Remarks Ranch Stock

The aircraft, engine or appliance identified **ABOVE** was repaired and/or inspected in accordance with current regulations of the Federal Aviation Administration.

Pertinent details of the repair / inspection are on file at this repair station under (as applicable)

Purchase Order # ~ Work Order # ~

Date 6/27/16 Signature [signature]

Certified Repair Station