HELI-ONE COLORADO EXTERNAL REPAIR TAG

EXTERNAL REPAIR TAG (UNSERVICEABLE PART)								
CM # 98930			CUSTOMER NAME: AIR MAUI					
PART NAME: Exterior Section Assy.			QUANTITY: 1		REPAIR WORK REQUESTED: Inspect			
PART NO: 0292378000			SERIAL NO: 167					
TSN: O/C	TSO: N/A		CSN: N/A	N/A	CSO: N/A	N/A		
REMOVED FROM								
	SERIES: Arriel 1		VARIANT: 1D1			MODULE # M03		
●	ENGINE TSN: N/A	ENGINE TSO: N/A	TSN-GEN	TSO-GEN	CSN-GEN	TSN-FT	TSO-FT	CSN-FT
	ENGINE S/N: N/A		N/A	N/A	N/A	N/A	N/A	N/A
	MODULE S/N: 9974		6678.10	3556.7	13705.02	N/A	N/A	N/A
○	COMPONENT NAME: ____							
○	COMPONENT P/N: ____		TSN	TSO		CSN		CSO
	COMPONENT S/N: ____		____	____		____		____
○	AC MODEL: ____	AC S/N: ____	REGISTRATION # ____	TOTAL TIME: ____		TOTAL CYCLES: ____		
REASON FOR REMOVAL / REPAIR(S) REQUIRED: Return to customer as is. Requires inspection to determine serviceability, IAW Arriel 1 OHM X 292 87 500 2						DATE REMOVED		TECH STAMP
NOTE ON THE REPAIR ORDER THAT INSPECTED, REPAIRED OR OVERHAULED PARTS RETURNED TO HELI-ONE MUST ACCOMPANY FAA FORM 8130-3, EASA FORM 1 OR EQUIVALENT.						9/14/2017		HELI-ONE 024 REPAIR CENTER