Heli-One Colorado

QAD-1032 External Repair Parts Tag
Heli-One American Support, LLC.
FAA CRS LH3D657L / EASA 145.4520

HELI-ONE COLORADO EXTERNAL REPAIR TAG

EXTERNAL REPAIR TAG (UNSERVICEABLE PART)

CM # 98930			CUSTOMER NAME: AIR MAUI				
PART NAME: Axial Screw			QUANTITY: 1		REPAIR WORK REQUESTED: Inspect		
PART NO: 0292437220			SERIAL NO: 3327B				
TSN: O/C	TSO: N/A		CSN: N/A	N/A	CSO: N/A	N/A	

REMOVED FROM

◉	SERIES: Arriel 1		VARIANT: 1D1			MODULE # M03		
	ENGINE TSN: N/A	ENGINE TSO: N/A	TSN-GEN	TSO-GEN	CSN-GEN	TSN-FT	TSO-FT	CSN-FT
	ENGINE S/N: N/A		N/A	N/A	N/A	N/A	N/A	N/A
	MODULE S/N: 9974		6678.10	3556.7	13705.02	N/A	N/A	N/A
○	COMPONENT NAME: _____							
	COMPONENT P/N: _____		TSN		TSO	CSN		CSO
	COMPONENT S/N: _____		_____		_____	_____		_____
○	AC MODEL: _____	AC S/N: _____	REGISTRATION # _____		TOTAL TIME: _____	TOTAL CYCLES: _____		

REASON FOR REMOVAL / REPAIR(S) REQUIRED: Return to customer as is. Requires inspection to determine serviceability, IAW Arriel 1 OHM X 292 87 500 2	DATE REMOVED	TECH STAMP
NOTE ON THE REPAIR ORDER THAT INSPECTED, REPAIRED OR OVERHAULED PARTS RETURNED TO HELI-ONE MUST ACCOMPANY FAA FORM 8130-3, EASA FORM 1 OR EQUIVALENT.	9/14/2017	HELI-ONE 024 REPAIR CENTER