SERVICEABLE Tag

F7.7.2-3

StandardAero SERVICEABLE Tag

| TCN | S/O | Model Number | Engine S/N |
|---|---|---|---|
| TW317585 | TRJ25 | 1D1 | 9950 |

| Part Number | Part S/N | QTY | Part Hours / Cycles |
|---|---|---|---|
| 0292253240 | ADH5394AD | 1 | N/A 8819.05 |

| Part Description | Customer |
|---|---|
| . TURBINE DISC, 1ST STAGE | 5 STAR GRAND CANYON HELICOPTER TOURS LLC |

Insp Notes:

Replace IAW DWI due to insufficient cycles remaining to make TBO.

Cycles rem: 1180.95 Cycles req'd: 5040

Inspected in OH IAW Arriel 1 OHM X 292 87 500 2 rev. 44

| Employee Number | | Date |
|---|---|---|
| 2973 | [x] Overhauled<br>[ ] Maintenance Comp. | 1/19/2023 11:09:24 PM |

SERVICEABLE