SERVICEABLE

☐ Repair ☐ Overhaul ☒ Inspection

Customer _____

Manufacturer _____

Reg _____ AFTT _____

Part Name Front Doubler - LH

Part Number 350A77-1146-20

Part Serial # NSN

TSN _____ TSO _____

TREM _____ Cycles _____

CREM _____ CSN _____

Remarks INSPECTED FOUND SERVICABLE NOT USED FROM ITEMS RCVD FROM PO # 560298

The aircraft, engine or appliance identified **ABOVE** was repaired and/or inspected in accordance with current regulations of the Federal Aviation Administration.

Pertinent details of the repair / inspection are on file at this repair station under (as applicable)

Purchase Order # 560298 Work Order # 82715

Date 18 JUL 2011 Signature _____

Certified Repair Station

EOOR 634D

Prism Helicopters Inc.
P.O. Box 872807
Wasilla, Alaska 99687